

ATTENTION

Due to a casting variation in the head from the OEM, the 1108-GS and 1109-GS cams may or may not have enough clearance to avoid interference of the two parts. Carefully inspect the clearance between the cam and the head where highlighted in red prior to re-assembly and running of the engine. Some hand grinding may be needed to create the required minimum clearance of 0.020" between the head and the intake lobes.

If you have additional questions, please contact Hot Cams customer service at 515-402-8005 or visit our Web site at hotcamsinc.com.

